

**Comments Form : Entry # 1764****Name**

Burt Handy

**Email**

[REDACTED]

**Phone****Address**

California  
United States  
[Map It](#)

**GSP Section for Comment/Question**

3.1 Hydrogeologic Conceptual Model

**GSP Comment/Question**

On Figures 3.1-03 and 3.1-04 the Ventura-Santa Clara River Syncline are shown on different locations on these Figures  
The Ventura-Santa Clara River Syncline and the Montalvo-South Mtn -Oak Ridge Fault Anticline are not shown on figures  
(Ventura Syncline) B-3.1-06, C 3.1-07, D 3.1-08 (Montalvo Anticline) b-3.1-06, 3.1-07

**Would you like to join the Mound Basin GSA Official Interested Parties List?**

Yes

**Beneficial Uses**

- Agriculture
- Municipal
- Industrial
- Residential
- Other

**Notes****MBGSA Public Comment/Question Notification (ID: 5ee3c8cd18bbb)**

added July 25, 2021 at 6:00 pm

WordPress successfully passed the notification email to the sending server.

**Notes****Jackie Lozano**[jackiel@unitedwater.org](mailto:jackiel@unitedwater.org)

added July 26, 2021 at 5:12 pm

Good morning, Mr. Handy, and thank you for your comment. I will make sure your comment is logged and passed along to our Executive Director Bryan Bondy.

Have a great day!

Best,

Jackie Lozano, Clerk of the Board for  
Mound Basin GSA